

Summary of Facility Information in the County of McCone

Owner Name and Address: Kalen Inc PO Box 75 Circle MT 59215 Phone: (406) 485-3645

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2900041	Circle Sinclair Services	MT Highway 200 & MT Highway 13	Circle	59215	(406) 485-3645

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
8 / 08 Currently In Use	612	10/1/1997 08 / No	Gasoline 6,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><div></div></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><div></div></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<div></div>	H	I	J	K	L	B		D	E	F	G	H	I	<div></div>	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<div></div>	H	I	J	K	L																					
B		D	E	F	G	H	I	<div></div>	K	L																						
9 / 09 Currently In Use	613	10/1/1997 08 / No	Diesel 2,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><div></div></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><div></div></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<div></div>	H	I	J	K	L	B		D	E	F	G	H	I	<div></div>	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<div></div>	H	I	J	K	L																					
B		D	E	F	G	H	I	<div></div>	K	L																						
10 / 10 Currently In Use	614	10/1/1997 08 / No	Diesel 2,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><div></div></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><div></div></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<div></div>	H	I	J	K	L	B		D	E	F	G	H	I	<div></div>	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<div></div>	H	I	J	K	L																					
B		D	E	F	G	H	I	<div></div>	K	L																						
11 / 11 Currently In Use	615	10/1/1997 08 / No	Diesel 6,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><div></div></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><div></div></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<div></div>	H	I	J	K	L	B		D	E	F	G	H	I	<div></div>	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<div></div>	H	I	J	K	L																					
B		D	E	F	G	H	I	<div></div>	K	L																						
12 / 12 Currently In Use	616	10/1/1997 08 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><div></div></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><div></div></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<div></div>	H	I	J	K	L	B		D	E	F	G	H	I	<div></div>	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<div></div>	H	I	J	K	L																					
B		D	E	F	G	H	I	<div></div>	K	L																						
13 / 13 Currently In Use	617	10/1/1997 08 / No	Diesel 2,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><div></div></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><div></div></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<div></div>	H	I	J	K	L	B		D	E	F	G	H	I	<div></div>	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<div></div>	H	I	J	K	L																					
B		D	E	F	G	H	I	<div></div>	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of McCone

Owner Name and Address: Kalen Inc PO Box 75 Circle MT 59215 Phone: (406) 485-3645

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2900042	Schmidts Mini Mall	MT Highway 200 & Main St	Circle	59215	(406) 485-2680

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
3 / 03 Currently In Use	618	10/1/1997 08 / No	Diesel 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	G	H	I	<input checked="" type="radio"/>	K	L			Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																							
4 / 04 Currently In Use	619	10/1/1997 08 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B	D	E	F	G	H	I	<input checked="" type="radio"/>	K	L			Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B	D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																							

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Mccone

Owner Name and Address: Circle Public School Dist 1 307 S Meridian Ave Circle MT 59215 Phone: (406) 485-3600

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2900874	Circle Public School Dist 1	307 S Meridian Ave	Circle	59215	(406) 485-3600

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / S2 Currently In Use	1890	8/1/1997 08 / No	Heating Oil 8,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	<div>Yes</div> <div>Yes Yes Yes</div>

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Mccone

Owner Name and Address: Circle Service Center Inc PO Box 176 Circle MT 59215 Phone: (406) 485-3663

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2903433	Circle Service Center Inc	203 1st Ave	Circle	59215	(406) 485-3663

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
7 / 07 Currently In Use	3802	11/1/1998 07 / No	Gasoline 6,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently In Use	3803	11/1/1998 07 / No	Gasoline 4,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
9 / 09 Currently In Use	3804	11/1/1998 07 / No	Diesel 6,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of McCone

Owner Name and Address: Hales Distributing 103 Main St PO Box 142 Circle MT 59215 Phone: (406) 485-2510

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2903684	Hales Distributing 103 Main St	103 Main St	Circle	59215	(406) 485-2510

TankID/Alt TankID	Tag	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met
Status	Numbe	Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C
1 / 05 Currently in Use	1267	9/12/1990 15 / No	Gasoline 5,000	Cathodically Protected Steel Double-Walled	Bare Steel Impressed Current	Safe Suction	<div style="display: flex; flex-wrap: wrap; gap: 2px;"> <div style="border: 1px solid black; padding: 1px;">A</div> <div style="border: 1px solid black; padding: 1px;">B</div> <div style="border: 1px solid black; padding: 1px;">C</div> <div style="border: 1px solid black; padding: 1px;">D</div> <div style="border: 1px solid black; padding: 1px;">E</div> <div style="border: 1px solid black; padding: 1px;">F</div> <div style="border: 1px solid black; padding: 1px;">G</div> <div style="border: 1px solid black; padding: 1px;">H</div> <div style="border: 1px solid black; padding: 1px;">I</div> <div style="border: 1px solid black; padding: 1px;">J</div> <div style="border: 1px solid black; padding: 1px;">K</div> <div style="border: 1px solid black; padding: 1px;">L</div> </div>	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of McCone

Owner Name and Address: Farmers Union Oil Co Circle PO Box 460 Circle MT 59215 Phone: (406) 485-3476

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2906376	Farmers Union Oil Co Circle	906 Avenue A	Circle	59215	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
8 / S08 Currently In Use	951	11/1/1998 07 / Ye	Gasoline 15,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B ● E F ● H I J K L</div> </div>	Yes Yes Yes Yes
9 / S09 Currently In Use	952	11/1/1998 07 / Ye	Gasoline 15,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B ● E F ● H I J K L</div> </div>	Yes Yes Yes Yes
10 / S10 Currently In Use	953	11/1/1998 07 / Ye	Diesel 15,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B ● E F ● H I J K L</div> </div>	Yes Yes Yes Yes
11 / S11 Currently In Use	954	11/1/1998 07 / Ye	Diesel 15,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B ● E F ● H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of McCone

Owner Name and Address: Farmers Union Oil Co Wolfpoint 60 US Highway 2 E Wolf Point MT 59201 Phone: (406) 653-1510

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614042	Agland Coop	MT Highway 13	Vida	59274	(406) 525-3207

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently In Use	4560	12/1/2001 04 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	4561	12/1/2001 04 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	4562	12/1/2001 04 / No	Diesel 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed